

BROCAS HSS ZANCO DE 1/2

| CODIGO | MEDIDIA | DEC. EQUIV. | L. TOTAL | L. CORTE | PZAS | PRECIO |
|--------|---------|-------------|----------|----------|------|------------|
| RDD33 | 33/64 | 0.5156 | 6" | 3" | 1/2 | \$499.26 |
| RDD34 | 17/32 | 0.5312 | 6" | 3" | 1/2 | \$499.26 |
| RDD35 | 35/64 | 0.5469 | 6" | 3" | 1/2 | \$523.82 |
| RDD36 | 9/16 | 0.5625 | 6" | 3" | 1/2 | \$522.26 |
| RDD37 | 37/64 | 0.5781 | 6" | 3" | 1/2 | \$572.92 |
| RDD38 | 19/32 | 0.5938 | 6" | 3" | 1/2 | \$572.92 |
| RDD39 | 39/64 | 0.6094 | 6" | 3" | 1/2 | \$581.10 |
| RDD40 | 5/8 | 0.6250 | 6" | 3" | 1/2 | \$580.72 |
| RDD41 | 41/64 | 0.6406 | 6" | 3" | 1/2 | \$622.03 |
| RDD42 | 21/32 | 0.6563 | 6" | 3" | 1/2 | \$630.21 |
| RDD43 | 43/64 | 0.6719 | 6" | 3" | 1/2 | \$646.59 |
| RDD44 | 11/16 | 0.6875 | 6" | 3" | 1/2 | \$643.85 |
| RDD45 | 45/64 | 0.7031 | 6" | 3" | 1/2 | \$682.05 |
| RDD46 | 23/32 | 0.7188 | 6" | 3" | 1/2 | \$682.05 |
| RDD47 | 47/64 | 0.7344 | 6" | 3" | 1/2 | \$706.61 |
| RDD48 | 3/4 | 0.7500 | 6" | 3" | 1/2 | \$705.44 |
| RDD49 | 49/64 | 0.7657 | 6" | 3" | 1/2 | \$763.90 |
| RDD50 | 25/32 | 0.7813 | 6" | 3" | 1/2 | \$763.90 |
| RDD51 | 51/64 | 0.7969 | 6" | 3" | 1/2 | \$793.90 |
| RDD52 | 13/16 | 0.8125 | 6" | 3" | 1/2 | \$793.90 |
| RDD53 | 53/64 | 0.8282 | 6" | 3" | 1/2 | \$826.64 |
| RDD54 | 27/32 | 0.8438 | 6" | 3" | 1/2 | \$826.64 |
| RDD55 | 55/64 | 0.8594 | 6" | 3" | 1/2 | \$848.46 |
| RDD56 | 7/8 | 0.8751 | 6" | 3" | 1/2 | \$848.46 |
| RDD57 | 57/64 | 0.8907 | 6" | 3" | 1/2 | \$883.94 |
| RDD58 | 29/32 | 0.9063 | 6" | 3" | 1/2 | \$883.94 |
| RDD59 | 59/64 | 0.9219 | 6" | 3" | 1/2 | \$963.05 |
| RDD60 | 15/16 | 0.9376 | 6" | 3" | 1/2 | \$963.05 |
| RDD61 | 61/64 | 0.9532 | 6" | 3" | 1/2 | \$1,003.98 |
| RDD62 | 31/32 | 0.9688 | 6" | 3" | 1/2 | \$1,003.98 |
| RDD63 | 63/64 | 0.9845 | 6" | 3" | 1/2 | \$1,102.20 |
| RDD64 | 1 | 1.0000 | 6" | 3" | 1/2 | \$1,101.03 |

BROCAS HSS ZANCO DE 1/2



| CODIGO | MEDIDIA | DEC. EQUIV. | L. TOTAL | L. CORTE | PZAS | PRECIO |
|--------|---------|-------------|----------|----------|------|------------|
| RDD65 | 1 1/64 | 1.0156 | 6" | 3" | 1/2 | \$1,909.74 |
| RDD66 | 1 1/32 | 1.0312 | 6" | 3" | 1/2 | \$1,693.52 |
| RDD67 | 1 3/64 | 1.0468 | 6" | 3" | 1/2 | \$1,988.86 |
| RDD68 | 1 1/16 | 1.0625 | 6" | 3" | 1/2 | \$1,645.11 |
| RDD69 | 1 5/64 | 1.0780 | 6" | 3" | 1/2 | \$1,901.56 |
| RDD70 | 1 3/32 | 1.0938 | 6" | 3" | 1/2 | \$2,160.74 |
| RDD71 | 1 7/64 | 1.1092 | 6" | 3" | 1/2 | \$1,964.31 |
| RDD72 | 1 1/8 | 1.1250 | 6" | 3" | 1/2 | \$1,765.15 |
| RDD73 | 1 9/64 | 1.1404 | 6" | 3" | 1/2 | \$2,035.24 |
| RDD74 | 1 5/32 | 1.1562 | 6" | 3" | 1/2 | \$2,299.88 |
| RDD75 | 1 11/64 | 1.1716 | 6" | 3" | 1/2 | \$2,106.17 |
| RDD76 | 1 3/16 | 1.1875 | 6" | 3" | 1/2 | \$1,972.49 |
| RDD77 | 1 13/64 | 1.2028 | 6" | 3" | 1/2 | \$2,130.73 |
| RDD78 | 1 7/32 | 1.2188 | 6" | 3" | 1/2 | \$2,073.43 |
| RDD79 | 1 15/64 | 1.2340 | 6" | 3" | 1/2 | \$2,272.59 |
| RDD80 | 1 1/4 | 1.2500 | 6" | 3" | 1/2 | \$2,499.03 |
| RDD81 | 1 17/64 | 1.2652 | 6" | 3" | 1/2 | \$2,384.45 |
| RDD82 | 1 9/32 | 1.2808 | 6" | 3" | 1/2 | \$2,343.53 |
| RDD83 | 1 19/64 | 1.2964 | 6" | 3" | 1/2 | \$2,357.17 |
| RDD84 | 1 5/16 | 1.3125 | 6" | 3" | 1/2 | \$2,302.60 |
| RDD85 | 1 21/64 | 1.3276 | 6" | 3" | 1/2 | \$2,449.93 |
| RDD86 | 1 11/32 | 1.3432 | 6" | 3" | 1/2 | \$2,496.31 |
| RDD87 | 1 23/64 | 1.3588 | 6" | 3" | 1/2 | \$2,518.13 |
| RDD88 | 1 3/8 | 1.3750 | 6" | 3" | 1/2 | \$2,542.69 |
| RDD89 | 1 25/64 | 1.3900 | 6" | 3" | 1/2 | \$2,744.57 |
| RDD90 | 1 13/32 | 1.4062 | 6" | 3" | 1/2 | \$2,845.52 |
| RDD91 | 1 27/64 | 1.4212 | 6" | 3" | 1/2 | \$2,894.62 |
| RDD92 | 1 7/16 | 1.4375 | 6" | 3" | 1/2 | \$2,946.46 |
| RDD93 | 1 29/64 | 1.4531 | 6" | 3" | 1/2 | \$3,003.75 |
| RDD94 | 1 15/32 | 1.4689 | 6" | 3" | 1/2 | \$3,033.76 |
| RDD95 | 1 31/64 | 1.4846 | 6" | 3" | 1/2 | \$3,047.40 |
| RDD96 | 1 1/2 | 1.5000 | 6" | 3" | 1/2 | \$3,063.77 |

Félix Ramírez Rentería 1140, Las
Ceibas, 47440 Lagos de Moreno, Jal.

INFO@TORNAL.COM.MX

 **474 121 0009**